

Drive Pulley 30-004-01K

When replacing the Drive Pulley 30-004-01K, Loctite 262 or equivalent must be applied to the bolts. Tighten the bolts to 18 Ft. / Lbs.

If the APU is equipped with the red multi-link belt, refer to Installation Bulletin # IB 5105 for instructions on removing and re-installing the belt.

